MITSUBISHI MOTOR SALES OF AMERICA, Inc.

TECHNICAL SERVICE BULLETIN

SUBJECT:
MPI CIRCUIT IN MONTERO SERVICE MANUAL – SERVICE MANUAL REVISION

NO. TSB-89-16-001
DATE June, 1989
MODEL Montero

TSB REVISION: 89-16-001

PURPOSE

This bulletin describes a correction to the 1989 Montero Service Manual. The Service Manual has typographic errors in the identification of two wire colors. As a reference to this bulletin, write the TSB number in the TSB Revision Box at the bottom of the affected page.

AFFECTED SERVICE MANUALS

1989 Montero Service Manual Volume 2, Page 8-56

SERVICE MANUAL CORRECTION

8-56 **WIRING HARNESS – M.P.I. Circuit**

5 M.P.I. CIRCUIT



015020

FILE UNDER: Group 16 Engine Electrical in the **Dealer Service Information** Binder.

CIRCULATE TO:
☐ GENERAL MANAGER ☐ PARTS MANAGER ☑ TECHNICIAN
☐ SERVICE ADVISOR ☑ SERVICE MANAGER ☐ WARRANTY PROCESSOR ☐ SALES MANAGER

(654)